Executive Summary – Enforcement Matter – Case No. 49759 Baytown Energy Center, LLC RN100226067 Docket No. 2014-1802-AIR-E

Order Type:

Findings Agreed Order

Findings Order Justification:

Three or more enforcement actions (NOVs, orders, etc.) over the prior five year period for the same violation(s).

Media:

AIR

Small Business:

Yes

Location(s) Where Violation(s) Occurred:

Baytown Energy Center, 8605 Farm-to-Market Road 1405, near Baytown, Chambers County

Type of Operation:

Natural gas-fired cogeneration power plant

Other Significant Matters:

Additional Pending Enforcement Actions: No

Past-Due Penalties: No

Other: N/A

Interested Third-Parties: None

Texas Register Publication Date: May 15, 2015

Comments Received: No

Penalty Information

Total Penalty Assessed: \$66,188

Amount Deferred for Expedited Settlement: \$0 Amount Deferred for Financial Inability to Pay: \$0

Total Paid to General Revenue: \$33,094

Total Due to General Revenue: \$0

Payment Plan: N/A

Supplemental Environmental Project ("SEP") Conditional Offset: \$33,094

Name of SEP: Railroad Commission of Texas (Third-Party Pre-Approved)

Compliance History Classifications:

Person/CN - Satisfactory Site/RN - Satisfactory

Major Source: Yes

Statutory Limit Adjustment: N/A Applicable Penalty Policy: April 2014

Executive Summary – Enforcement Matter – Case No. 49759 Baytown Energy Center, LLC RN100226067 Docket No. 2014-1802-AIR-E

Investigation Information

Complaint Date(s): N/A **Complaint Information**: N/A

Date(s) of Investigation: September 30, 2014 through October 10, 2014

Date(s) of NOE(s): November 19, 2014

Violation Information

- 1. Failed to include a signed certification of accuracy and completeness with a report required by Federal Operating Permit ("FOP") No. O2133 [30 Tex. Admin. Code §§ 122.143(4) and (15) and 122.165(a)(7), Tex. Health & Safety Code § 382.085(b), and FOP No. O2133, General Terms and Conditions].
- 2. Failed to operate within the permitted concentration limits for nitrogen oxides ("NOx") and ammonia ("NH3") from the Heat Recovery Steam Generating ("HRSG") Stack, Emission Point Numbers ("EPNs") CTG1, CTG2, and CTG3 [30 Tex. Admin. Code §§ 101.20(3), 116.115(c), and 122.143(4), Tex. Health & Safety Code § 382.085(b), New Source Review Permit Nos. 41996, PSDTX953, and No20, Special Conditions Nos. 5 and 8, and FOP No. O2133, Special Terms and Conditions No. 7].

Corrective Actions/Technical Requirements

Corrective Action(s) Completed:

The Respondent has implemented the following corrective measures:

- a. On December 16, 2013, performed maintenance on the programmable logic controller to prevent inaccurate readings from the continuous emissions monitoring system;
- b. On February 28, 2014, replaced and upgraded the catalyst for EPN CTG3 to prevent NOx and NH3 concentration limit exceedances from EPN CTG3;
- c. On June 17, 2014, repaired the HRSG Unit tube leak that was causing inaccurate temperature readings from one of the thermocouples that indicate HRSG Unit temperature;
- d. By August 20, 2014, conducted training on procedures for startup and for monitoring the function of various components to maintain compliance, including checking the control valve and the NH3 stop valve, for operators at the Plant;

Executive Summary – Enforcement Matter – Case No. 49759 Baytown Energy Center, LLC RN100226067 Docket No. 2014-1802-AIR-E

e. On October 23, 2014, submitted a signed certification of accuracy and completeness for the deviation report dated February 28, 2014 for the reporting period from August 5, 2013 through February 4, 2014;

f. On November 24, 2014, replaced and upgraded the catalyst for EPN CTG2 to prevent NOx and NH3 concentration limit exceedances from EPN CTG2; and

g. On February 14, 2015, replaced and upgraded the catalyst for EPN CTG1 to prevent NOx and NH3 concentration limit exceedances from EPN CTG1.

Technical Requirements:

The Order will require the Respondent to implement and complete a SEP (See SEP Attachment A).

Litigation Information

Date Petition(s) Filed: N/A
Date Answer(s) Filed: N/A
SOAH Referral Date: N/A
Hearing Date(s): N/A
Settlement Date: N/A

Contact Information

TCEQ Attorney: N/A

TCEQ Enforcement Coordinator: Rachel Bekowies, Enforcement Division, Enforcement Team 4, MC 149, (512) 239-2608; Candy Garrett, Enforcement Division, MC 219, (512) 239-1456

TCEQ SEP Coordinator: Stuart Beckley, SEP Coordinator, Enforcement Division, MC 219, (512) 239-3565

Respondent: W. Thaddeus Miller, Chief Legal Officer, Baytown Energy Center, LLC, P.O. Box 840, Baytown, Texas 77522

Anthony Ligato, Plant Manager, Baytown Energy Center, LLC, P.O. Box 840, Baytown, Texas 77522

Respondent's Attorney: N/A

*		
		a:
		e ^r
		1 (%)
		v _e ž.
		y

Attachment A

Docket Number: 2014-1802-AIR-E

SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:	Baytown Energy Center, LLC
Penalty Amount:	Sixty-Six Thousand One Hundred Eighty-Eight Dollars (\$66,188)
SEP Offset Amount:	Thirty-Three Thousand Ninety-Four Dollars (\$33,094)
Type of SEP:	Contribution to a Third-Party Pre-Approved SEP
Third-Party Administrator:	Railroad Commission of Texas
Project Name:	Alternative Fuels Clean School Bus Replacement Program
Location of SEP:	Statewide, Preference for Chambers County

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative penalty amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The SEP Offset Amount is set forth above and such offset is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Administrator named above. The contribution will be to the **Railroad Commission of Texas** for the *Alternative Fuels Clean School Bus Replacement Program*. The contribution will be used in accordance with the SEP between the Third-Party Administrator and the TCEQ (the "Project"). Specifically, the contribution will be used to reduce nitrogen oxides, volatile organic compounds, carbon monoxide, and particulate matter emissions by replacing older diesel buses with newer buses that meet more stringent emission standards.

The Third-Party Administrator shall use the SEP Offset Amount for up to 100% of the purchase price of a propane or natural gas powered school bus that is model year 2010 or newer to public school districts and public charter schools to replace a diesel school bus that is model year 2002 or older. The SEP will be done in accordance with all federal, state, and local environmental laws and regulations.

All dollars contributed will be used for the direct cost of implementing the Project, including but not limited to supplies, materials, and equipment. Any portion of this contribution that is not spent on the specifically identified SEP may, at the discretion of the Executive Director ("ED"), be applied to another pre-approved SEP.

Baytown Energy Center, LLC Agreed Order - Attachment A

The Respondent's signature affixed to this Agreed Order certifies that it has no prior commitment to make this contribution and that it is being contributed solely in an effort to settle this enforcement action. The Respondent shall not profit in any manner from this SEP.

b. Environmental Benefit

This SEP will directly benefit air quality by reducing harmful exhaust emissions which contribute to the formation of ozone and may cause or exacerbate a number of respiratory diseases, including asthma. In addition, by encouraging less school bus idling, this SEP contributes to public awareness of environmental matters.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Administrator and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Administrator. The Respondent shall make the check payable to **Railroad Commission of Texas SEP** and shall mail the contribution with a copy of the Agreed Order to:

Alternative Energy Division Railroad Commission of Texas P.O. Box 12967 Austin, Texas 78711-2967

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the Enforcement Division SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount due to the Third-Party Administrator. The Respondent shall mail a copy of the check and transmittal letter to:

Texas Commission on Environmental Quality Enforcement Division Attention: SEP Coordinator, MC 219 P.O. Box 13087 Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this Attachment A, including full expenditure of the SEP Offset Amount and submittal of the required reporting described in Sections 2 and 3 above, the ED may require immediate payment of all or part of the SEP Offset Amount.

In the event the ED determines that the Respondent failed to fully implement and complete the Project, the Respondent shall remit payment for all or a portion of the SEP Offset Amount, as determined by the ED, and as set forth in the attached Agreed Order. After receiving notice of failure to complete the SEP, the Respondent shall include the docket number of the attached Agreed Order and a note that the enclosed payment is for the reimbursement of a SEP; shall make the check payable to "Texas Commission on Environmental Quality;" and shall mail it to:

Texas Commission on Environmental Quality Litigation Division Attention: SEP Coordinator, MC 175 P.O. Box 13087 Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP made by or on behalf of the Respondent, must include a clear statement that **the Project was performed as part of the settlement of an enforcement action brought by the TCEQ**. Such statements include advertising, public relations, and press releases.

6. Recognition

The Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.

Penalty Calculation Worksheet (PCW) Policy Revision 4 (April 2014) PCW Revision March 26, 2014 Assigned 24-Nov-2014 PCW 6-Mar-2015 Screening 3-Dec-2014 **EPA Due** RESPONDENT/FACILITY INFORMATION Respondent Baytown Energy Center, LLC Reg. Ent. Ref. No. Facility/Site Region 12-Houston Major/Minor Source Major **CASE INFORMATION** Enf./Case ID No. 49759 Docket No. 2014-1802-AIR-E Media Program(s) Air No. of Violations 2 Order Type Findings Government/Non-Profit No Enf. Coordinator Rachel Bekowies Multi-Media EC's Team Enforcement Team 4 Admin. Penalty \$ Limit Minimum \$0 Maximum \$25,000

		Penal	lty Calculati	on Section	**************************************	***************************************
TOTAL BASE PENA	ALTY (St	ım of violation	base penaltie	es)	Subtotal 1	\$37,500
ADJUSTMENTS (+ Subtotals 2-7 are of	/-) TO S	SUBTOTAL 1 ultiplying the Total Base	e Penalty (Subtotal 1) b	y the indicated percentage.		
Compliance Hi	story		29.0%	Enhancement Sul	ototals 2, 3, & 7	\$10,875
Notes		taining a denial of I		violations and one agre for one Notice of Intent		
Culpability	No		0.0%	Enhancement	Subtotal 4	\$0
Notes		The Respondent do	es not meet the cu	ulpability criteria.		
Good Faith Eff	ort to Cor	nply Total Adjust	ments		Subtotal 5	-\$937
Economic Ben	efit Total EB Ai I Cost of Com		50.0% En *Capped a	hancement* t the Total EB \$ Amount	Subtotal 6	\$18,750
SUM OF SUBTOTA	LS 1-7				Final Subtotal	\$66,188
OTHER FACTORS A				0.0%	Adjustment	\$0
Notes						
				Final F	Penalty Amount	\$66,188
STATUTORY LIMIT	T ADJUS	TMENT		Final As	sessed Penalty	\$66,188
DEFERRAL Reduces the Final Assessed Pe	nalty by the i	ndicated percentage. (I	Enter number only; e.g	0.0% Reduction . 20 for 20% reduction.)	Adjustment	\$0
Notes		No deferral is rec	commended for Fin	dings Orders.		
PAYABLE PENALTY	1					\$66,188

PCW

Policy Revision 4 (April 2014) PCW Revision March 26, 2014

Respondent Baytown Energy Center, LLC

Case ID No. 49759

Reg. Ent. Reference No. RN100226067

Media [Statute] Air

Enf. Coordinator Rachel Bekowies

Component	ory Site Enhancement (Subtotal 2) Number of	Enter Number Here	Adjust.
NOVs	Written notices of violation ("NOVs") with same or similar violations as those in the current enforcement action (number of NOVs meeting criteria)	2	10%
	Other written NOVs	Ó	0%
	Any agreed final enforcement orders containing a denial of liability (number of orders meeting criteria)	1	20%
Orders	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	0	0%
Judgments and Consent	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (number of judgments or consent decrees meeting criteria)	0	0%
Decrees	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	0	0%
Convictions	Any criminal convictions of this state or the federal government (<i>number of counts</i>)	0	0%
Emissions	Chronic excessive emissions events (number of events)	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which notices were submitted)	1	-1%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which violations were disclosed)	0	0%
	Pie	ase Enter Yes or No	
	Environmental management systems in place for one year or more	No	0%
Other	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%
eat Violator (Adjustment Per	centage (Sub	total 2)
No		centage (Sub	total 3)
npliance Histo	ory Person Classification (Subtotal 7)		
Satisfactory	Performer Adjustment Per	centage (Subi	total 7)
npliance Histo	ry Summary		
Compliance History Notes	Enhancement for two NOVs with same/similar violations and one agreed order con of liability. Reduction for one Notice of Intent to conduct an audit.	taining a denial	

PCW	ANY CONTRACTOR CONTRAC	Screening Date	Sc
olicy Revision 4 (April 2014,		Respondent Case ID No.	
W Revision March 26, 201	7.277	. Reference No.	Rea. Ent. R
		Media [Statute]	
		nf. Coordinator	
		Violation Number	Vi
	30 Tex. Admin. Code §§ 122,143(4) and (15) and 122.165(a)(7), Tex. Health & Safety Code § 382.085(b), and Federal Operating Permit ("FOP") No. O2133, General Terms and Conditions	Rule Cite(s)	
s, l	Failed to include a signed certification of accuracy and completeness with a report required by FOP No. O2133. Specifically, the deviation report dated February 28, 2014 for the reporting period from August 5, 2013 through February 4, 2014 was submitted to the TCEQ Houston Regional Office without a signed certification of accuracy and completeness.	olation Description	Violat
ty \$25,000	Base Penalty		
	ty and Human Health Matrix Harm		-> Environm
	Major Moderate Minor	Release Actual	OR
		Potential	
		mmatic Matrix	>Programn
	Major Moderate Minor X Percent 15.0%	Falsification	
	100% of the rule requirement was not mot	atrix	Matrix
	100% of the rule requirement was not met.	otes	Notes
50	Adjustment \$21,250		
\$3,750			
		ivente	iolation Eve
		vents	ioration Eve
	/iolation Events 1 231 Number of violation days	Number of \	
	daily weekly		
\$3,750	monthly quarterly semiannual annual single event	mark only one with an x	
1.	ent is recommended for the one report submitted without the required certification.	One single ev	
on \$937	Ply 25.0% Reduction Before NOE/NOV NOE/NOV to EDPRP/Settlement Offer	Efforts to Com	ood Faith Ef
	Extraordinary Cordinary X		
	N/A (mark with x)		
	Notes The Respondent completed corrective actions on October 23, 2014, prior to the November 19, 2014 Notice of Enforcement.		
al \$2,813	Violation Subtotal		
	this violation Statutory Limit Test	Benefit (EB) for	conomic Ber
al \$5,776	d EB Amount \$8 Violation Final Penalty Total	Estimate	
\$5,776	This violation Final Assessed Penalty (adjusted for limits)		

	—	conomic	Dellelit	AAO	rksneet		
Respondent	Baytown Ener	gy Center, LLC	Annia managan				
Case ID No.	49759						
eg. Ent. Reference No.	RN100226067	7					
Media	Air						Years of
Violation No.						Percent Interest	Depreciation
Totalion ite.	-					5.0	15
	Item Cost	Date Required	Final Date	Vrc	Interest Saved	Onetime Costs	EB Amount
Item Description		the second second second		•			
Delayed Costs	,						
Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/Construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
	CHARLES AND ARRESTS BUT AND ARRESTS	A CONTROL ESTREMENTAL DE CONTROL		100000000000000000000000000000000000000	escale of the control		STATE OF THE STATE
Remediation/Disposal				0.00	\$0	n/a	\$0
Remediation/Disposal Permit Costs				0.00	\$0 \$0	n/a n/a	\$0 \$0
	\$250 Estimated cos		23-Oct-2014 ed certification	0.00	\$0 \$8		\$0 \$8
Permit Costs	Estimated cos February 2	t to submit a sign 8, 2014 for the re	ed certification porting period f	0.00 0.63 of accur	\$0 \$8 racy and complete gust 5, 2013 thro	n/a n/a	\$0 \$8 on report dated 4. The Date
Permit Costs Other (as needed)	Estimated cos February 2 Requir	t to submit a sign 8, 2014 for the re ed is the date the	ed certification porting period f deviation repo	0.00 0.63 of accur rom Au rt was o	\$0 \$8 racy and complete gust 5, 2013 thro due. The Final Dat	n/a n/a eness for the deviation ugh February 4, 201	\$0 \$8 on report dated 4. The Date pliance.
Permit Costs Other (as needed) Notes for DELAYED costs	Estimated cos February 2 Requir	t to submit a sign 8, 2014 for the re ed is the date the	ed certification porting period f deviation repo	0.00 0.63 of accur rom Au rt was o	\$0 \$8 racy and complete gust 5, 2013 thro due. The Final Dat	n/a n/a eness for the deviation ugh February 4, 201 e is the date of com	\$0 \$8 on report dated 4. The Date pliance.
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel	Estimated cos February 2 Requir	t to submit a sign 8, 2014 for the re ed is the date the	ed certification porting period f deviation repo	of accurry was of accurry was of accurry accurry accurry accurate	\$0 \$8 racy and complete gust 5, 2013 thro due. The Final Dat ng item (except 1 \$0 \$0	n/a n/a n/a eness for the deviation of t	\$0 \$8 on report dated 4. The Date pliance. led costs)
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling	Estimated cos February 2 Requir	t to submit a sign 8, 2014 for the re ed is the date the	ed certification porting period f deviation repo	0.00 0.63 of accurry was of accurry	\$0 \$8 racy and complete gust 5, 2013 thro due. The Final Dat ing item (except 1 \$0 \$0 \$0	n/a n/a n/a n/a ness for the deviation of the deviation o	\$0 \$8 on report dated 4. The Date pliance. 4d costs 50 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/Equipment	Estimated cos February 2 Requir	t to submit a sign 8, 2014 for the re ed is the date the	ed certification porting period f deviation repo	0.00 0.63 of accurate was contact was contact was contact of 0.00 0.00 0.00	\$0 \$8 racy and complete gust 5, 2013 thro due. The Final Dat ig Item (except 1 \$0 \$0 \$0	n/a n/a n/a n/a ness for the deviati ugh February 4, 201 e is the date of com for one-time avoid \$0 \$0 \$0 \$0 \$0	\$0 \$8 on report dated 4. The Date pliance. led costs) \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/Equipment Financial Assurance [2]	Estimated cos February 2 Requir	t to submit a sign 8, 2014 for the re ed is the date the	ed certification porting period f deviation repo	0.00 0.63 of accurry from Au rt was c enterin 0.00 0.00 0.00 0.00	\$0 \$8 racy and complete gust 5, 2013 thro due. The Final Dat gitem (except 1 \$0 \$0 \$0 \$0 \$0	n/a n/a n/a n/a n/a ness for the deviation ugh February 4, 201 e is the date of com for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$8 on report dated 4. The Date pliance. led costs) \$0 \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/Equipment Financial Assurance [2] ONE-TIME avoided costs [3]	Estimated cos February 2 Requir	t to submit a sign 8, 2014 for the re ed is the date the	ed certification porting period f deviation repo	0.00 0.63 of accurrent was of enterin 0.00 0.00 0.00 0.00 0.00	\$0 \$8 racy and complete gust 5, 2013 thro due. The Final Dat ng item (except 1 \$0 \$0 \$0 \$0 \$0	n/a n/a n/a n/a n/a ness for the deviation of the deviati	\$0 \$8 on report dated 4. The Date pliance. ed costs \$0 \$0 \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/Equipment Financial Assurance [2]	Estimated cos February 2 Requir	t to submit a sign 8, 2014 for the re ed is the date the	ed certification porting period f deviation repo	0.00 0.63 of accurry from Au rt was c enterin 0.00 0.00 0.00 0.00	\$0 \$8 racy and complete gust 5, 2013 thro due. The Final Dat gitem (except 1 \$0 \$0 \$0 \$0 \$0	n/a n/a n/a n/a n/a ness for the deviation ugh February 4, 201 e is the date of com for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$8 on report dated 4. The Date pliance. led costs) \$0 \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/Equipment Financial Assurance [2] ONE-TIME avoided costs [3]	Estimated cos February 2 Requir	t to submit a sign 8, 2014 for the re ed is the date the	ed certification porting period f deviation repo	0.00 0.63 of accurrent was of enterin 0.00 0.00 0.00 0.00 0.00	\$0 \$8 racy and complete gust 5, 2013 thro due. The Final Dat ng item (except 1 \$0 \$0 \$0 \$0 \$0	n/a n/a n/a n/a n/a ness for the deviation of the deviati	\$0 \$8 on report dated 4. The Date pliance. ed costs \$0 \$0 \$0 \$0

F		Baytown Energy Center, LLC	PCW Policy Revision 4 (April 2014)
Reg. Ent. Ref Medi Enf. C	a [Statute] Coordinator	RN100226067	PCW Revision March 26, 2014
Viola	ation Number Rule Cite(s)	2 30 Tex. Admin. Code §§ 101.20(3), 116.115(c), and 122.143(4), Tex. Safety Code § 382.085(b), New Source Review Permit Nos. 41996, PSDT N020, Special Conditions Nos. 5 and 8, and FOP No. O2133, Special Te Conditions No. 7	X953, and
Violatio	n Description	Failed to operate within the permitted concentration limits for nitroger ("NOx") and ammonia ("NH3") from the Heat Recovery Steam Generating Stack, Emission Point Numbers ("EPNs") CTG1, CTG2, and CTG3. Specifi NOx concentration limit of 3.5 parts per million by volume on a dry basis of based on a three-hour rolling average concentration, was exceeded five to EPN CTG1 from September 28, 2013 through April 16, 2014, two times CTG2 from October 26, 2013 through December 8, 2013, and nine times CTG3 from September 3, 2013 through June 3, 2014. The NH3 concentr of 10 ppmvd, based on a one-hour rolling average concentration, was exceeded five time from EPN CTG1 on February 12, 2014, nine times from EPN CTG September 4, 2013 through March 5, 2014, and five times from EPN CTG September 4, 2013 through December 12, 2013.	g ("HRSG") ically, the ("ppmvd"), dimes from from EPN from EPN ation limit deeded one 2 from
	•		se Penalty \$25,000
>> Environme	Release Actual	ty and Human Health Matrix Harm Major Moderate Minor x	
	Potential	Percent 15.0%	
>>Programma	tic Matrix Falsification	Major Moderate Minor	
		Percent 0.0%	
Matrix Notes	ppmvd and environment h	instances of non-compliance, NOx concentrations ranged from 3.6 ppmvd NH3 concentrations ranged from 10.1 ppmvd to 18.4 ppmvd. Human healt as been exposed to insignificant amounts of pollutants that do not exceed ective of human health or environmental receptors as a result of the violated to the contract of the cont	h or the levels that
		Adjustment	\$21,250
			\$3,750
/iolation Event		iolation Events 9 273 Number of violation	davs
		daily weekly	
	mark only one with an x	monthly quarterly x Violation Bas semiannual annual	e Penalty \$33,750
		Ty events, three each per EPN, are recommended based on the instances e that occurred during the period of September 3, 2013 through June 3, 2	
Good Faith Effo	rts to Comp	•	Reduction \$0
		Before NOE/NOV NOE/NOV to EDPRP/Settlement Offer Extraordinary Ordinary N/A x ((mark with x)	
		Notes The Respondent does not meet the good faith effort criteria for this violation.	Subsect 1
Economic Benel	fit (EB) for		Subtotal \$33,750
		d EB Amount \$182,693 Violation Final Pena	
		This violation Final Assessed Penalty (adjusted for	-
		in the state of th	4007,113

	Baytown Ener						
Case ID No.	80 °						
g. Ent. Reference No.	. RN100226067	•					
Media							Years of
Violation No.	. 2					Percent Interest	Depreciatio
Section 1						5.0	1
	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
Item Description						enemine edad	
	· NO CONTINUE OF F						
Delayed Costs					·		
Equipment	\$1,800,000	3-Sep-2013	14-Feb-2015	1.45	\$8,696	\$173,918	\$182,614
Buildings				0.00	\$0	\$0	\$0
Other (as needed)	\$1,000	3-Sep-2013	17-Jun-2014	0.79	\$3	\$52	\$55
Engineering/Construction			100	0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System	4500	3 6 3015	20.4 - 2014	0.00	\$0	n/a	\$0
Training/Sampling Remediation/Disposal	\$500	3-Sep-2013	20-Aug-2014	0.96	\$24	n/a	<u>\$24</u>
Permit Costs				0.00	\$0 \$0	n/a n/a	\$0 \$0
		JL		0.00			
Other (as needed) Notes for DELAYED costs	costs to repa one of the the startup and fo the control	air the HRSG Unit irmocouples that i or monitoring the valve and the NH.	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for)) that nit tem ous con operat	\$0 PNs CTG1, CTG2, was causing inaccuperature; conduction maintenance to maintenance at the Plant; and the Plan	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, inclu- and perform mainter readings from the c	\$0 00). Estimate eadings from procedures foulding checking ance on the
	costs to repa one of the the startup and fo the control programm emissions mo The February 2014 Final	air the HRSG Unit rmocouples that I or monitoring the valve and the NH. nable logic contro onitoring system. v 14, 2015 Final E Date is the date I	tube leak (\$500 ndicate HRSG U function of varios stop valve, for liler ("PLC") (\$50 The September bate is the date the HRSG Unit to	s for El 0) that nit tem ous con operat 00) to p 3, 201 all cata ube lea	\$0 PNS CTG1, CTG2, was causing inaccurate; conductions to maint tors at the Plant; a prevent inaccurate 3 Date Required is lysts were replace k was repaired, and	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, inclu- and perform mainter readings from the c the first date of no d and upgraded by, and maintenance on t	\$0 00). Estimate eadings from procedures for iding checking ance on the continuous n-compliance. The June 17, he PLC was
Notes for DELAYED costs	costs to repa one of the the startup and for the control programm emissions mo The February 2014 Final performed by	air the HRSG Unit rmocouples that if or monitoring the valve and the NH: nable logic contro onitoring system. y 14, 2015 Final E Date is the date if this date. The Au	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for liler ("PLC") (\$50 The September late is the date the HRSG Unit tigust 20, 2014 for a first series of the late is the l	s for EF)) that nit tem bus com operat 00) to p 3, 201 all cata ube lea	\$0 PNs CTG1, CTG2, was causing inaccuperature; conductors to maint tors at the Plant; apprevent inaccurate 3 Date Required is lysts were replace k was repaired, and the is the date train	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, inclu- and perform mainter readings from the c the first date of noi d and upgraded by, and maintenance on t ning for operators w	\$0 00). Estimate eadings from procedures for iding checking ance on the continuous n-compliance. The June 17, he PLC was as conducted.
	costs to repa one of the the startup and for the control programm emissions mo The February 2014 Final performed by	air the HRSG Unit rmocouples that if or monitoring the valve and the NH: nable logic contro onitoring system. y 14, 2015 Final E Date is the date if this date. The Au	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for liler ("PLC") (\$50 The September late is the date the HRSG Unit tigust 20, 2014 for a first series of the late is the l	s for EF)) that nit tem bus com operat 00) to p 3, 201 all cata ube lea	\$0 PNs CTG1, CTG2, was causing inaccuperature; conductors to maint tors at the Plant; apprevent inaccurate 3 Date Required is lysts were replace k was repaired, and the is the date train	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, inclu- and perform mainter readings from the c the first date of no d and upgraded by, and maintenance on t	\$0 00). Estimate eadings from procedures for iding checking ance on the continuous n-compliance. The June 17, he PLC was as conducted.
Notes for DELAYED costs Avoided Costs Disposal Personnel	costs to repa one of the the startup and for the control programm emissions mo The February 2014 Final performed by	air the HRSG Unit rmocouples that if or monitoring the valve and the NH: nable logic contro onitoring system. y 14, 2015 Final E Date is the date if this date. The Au	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for liler ("PLC") (\$50 The September late is the date the HRSG Unit tigust 20, 2014 for a first series of the late is the l	s for EI) that nit tem ous con operat 00) to p 3, 201 all cata ube lea inal Da enterin 0.00 0.00	PNs CTG1, CTG2, was causing inaccurate; conductions at the Plant; corevent inaccurate 3 Date Required is lysts were replace k was repaired, and is the date training item (except 1 \$0 \$0 \$0	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, inclu- and perform mainter readings from the c the first date of no d and upgraded by and maintenance on t ning for operators w for one-time avoid \$0 \$0 \$0	\$0 00). Estimate eadings from procedures for iding checking ance on the continuous n-compliance. The June 17, he PLC was as conducted.
Notes for DELAYED costs Avoided Costs Disposal Personnel ection/Reporting/Sampling	costs to repa one of the the startup and for the control programm emissions mo The February 2014 Final performed by	air the HRSG Unit rmocouples that if or monitoring the valve and the NH: nable logic contro onitoring system. y 14, 2015 Final E Date is the date if this date. The Au	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for liler ("PLC") (\$50 The September late is the date the HRSG Unit tigust 20, 2014 for a first series of the late is the l	s for El) that nit tem ous com operat 00) to p 3, 201 all cata ube lea Final Da enterin 0.00 0.00	PNs CTG1, CTG2, was causing inaccurate; conductions at the Plant; corevent inaccurate 3 Date Required is lysts were replace k was repaired, and is the date training item (except 1 \$0 \$0 \$0 \$0	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, inclu- and perform mainter readings from the c the first date of noi d and upgraded by. nd maintenance on t ning for operators w for one-time avoid \$0 \$0 \$0 \$0	\$0 00). Estimate eadings from procedures for ding checking ance on the continuous n-compliance. The June 17, he PLC was as conducted. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Avoided Costs Avoided Costs Disposal Personnel ection/Reporting/Sampling Supplies/Equipment	costs to repa one of the the startup and for the control programm emissions mo The February 2014 Final performed by	air the HRSG Unit rmocouples that if or monitoring the valve and the NH: nable logic contro onitoring system. y 14, 2015 Final E Date is the date if this date. The Au	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for liler ("PLC") (\$50 The September late is the date the HRSG Unit tigust 20, 2014 for a first series of the late is the l	s for EP) that nit tem pus con operat 00) to p 3, 201 all cata ube lea inal Da enterin 0.00 0.00 0.00	\$0 PNs CTG1, CTG2, was causing inaccuperature; conductions at the Plant; appropriate inaccurate 3 Date Required is lysts were replace k was repaired, and the is the date training item (except 1 \$0 \$0 \$0 \$0 \$0	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, inclu- and perform mainter readings from the c the first date of noi d and upgraded by, nd maintenance on t ning for operators w for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 00). Estimate eadings from procedures for diding checking ance on the continuous n-compliance. The June 17, he PLC was as conducted. ** ** ** ** ** ** ** ** **
Avoided Costs Avoided Costs Disposal Personnel ection/Reporting/Sampling Supplies/Equipment Financial Assurance [2]	costs to repa one of the the startup and for the control programm emissions mo The February 2014 Final performed by	air the HRSG Unit rmocouples that if or monitoring the valve and the NH: nable logic contro onitoring system. y 14, 2015 Final E Date is the date if this date. The Au	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for liler ("PLC") (\$50 The September late is the date the HRSG Unit tigust 20, 2014 for a first series of the late is the l	s for EPD) that nit tempous con operate 00) to p 33, 201 all cata ube lead in all cata ube le	\$0 PNs CTG1, CTG2, was causing inaccuperature; conductors at the Plant; correvent inaccurate 3 Date Required is lysts were replace k was repaired, at the date training item (except 1 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, included and perform mainter readings from the color of the first date of not d and upgraded by, and maintenance on t ning for operators w for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 00). Estimate eadings from procedures for diding checking hance on the continuous n-compliance. The June 17, he PLC was as conducted. ** ** ** ** ** ** ** ** **
Avoided Costs Avoided Costs Disposal Personnel ection/Reporting/Samplint Supplies/Equipment Financial Assurance [2] ONE-TIME avoided costs [3]	costs to repa one of the the startup and for the control programm emissions mo The February 2014 Final performed by	air the HRSG Unit rmocouples that if or monitoring the valve and the NH: nable logic contro- pritoring system. y 14, 2015 Final E Date is the date if this date. The Au	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for liler ("PLC") (\$50 The September late is the date the HRSG Unit tigust 20, 2014 for a first series of the late is the l	s for EP) that nit tempus con operat 00) to p 3, 201 all cata ube lea inal Da enterin 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	PNs CTG1, CTG2, was causing inaccuperature; conduction ponents to maint cors at the Plant; a prevent inaccurate 3 Date Required is lysts were replace k was repaired, at a te is the date training item (except 1 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, included and perform mainter readings from the color of d and upgraded by and maintenance on to ning for operators w or one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 00). Estimate eadings from procedures for uding checking nance on the continuous n-compliance. The June 17, he PLC was as conducted. ed costs) \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$
Avoided Costs Avoided Costs Disposal Personnel ection/Reporting/Sampling Supplies/Equipment Financial Assurance [2]	costs to repa one of the the startup and for the control programm emissions mo The February 2014 Final performed by	air the HRSG Unit rmocouples that if or monitoring the valve and the NH: nable logic contro- pritoring system. y 14, 2015 Final E Date is the date if this date. The Au	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for liler ("PLC") (\$50 The September late is the date the HRSG Unit tigust 20, 2014 for a first series of the late is the l	s for EPD) that nit tempous con operate 00) to p 33, 201 all cata ube lead in all cata ube le	\$0 PNs CTG1, CTG2, was causing inaccuperature; conductors at the Plant; correvent inaccurate 3 Date Required is lysts were replace k was repaired, at the date training item (except 1 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, included and perform mainter readings from the color of the first date of not d and upgraded by, and maintenance on t ning for operators w for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 00). Estimate eadings from procedures for the continuous n-compliance. The June 17, he PLC was as conducted \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Avoided Costs Avoided Costs Disposal Personnel ection/Reporting/Samplies Supplies/Equipment Financial Assurance [2] ONE-TIME avoided costs [3]	costs to repa one of the the startup and for the control programm emissions mo The February 2014 Final performed by	air the HRSG Unit rmocouples that if or monitoring the valve and the NH: nable logic contro- pritoring system. y 14, 2015 Final E Date is the date if this date. The Au	tube leak (\$500 ndicate HRSG U function of vario 3 stop valve, for liler ("PLC") (\$50 The September late is the date the HRSG Unit tigust 20, 2014 for a first series of the late is the l	s for EP) that nit tempus con operat 00) to p 3, 201 all cata ube lea inal Da enterin 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	PNs CTG1, CTG2, was causing inaccuperature; conduction ponents to maint cors at the Plant; a prevent inaccurate 3 Date Required is lysts were replace k was repaired, at a te is the date training item (except 1 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	n/a and CTG3 (\$1,800,0 urate temperature r t training (\$500) on ain compliance, included and perform mainter readings from the color of d and upgraded by and maintenance on to ning for operators w or one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 00). Estimate eadings from procedures for uding checking nance on the continuous n-compliance. The June 17, he PLC was as conducted. ed costs) \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$

To request a more accessible version of this report, please contact the TCEQ Help Desk at (512) 239-4357.



Compliance History Report

PUBLISHED Compliance History Report for CN600376073, RN100226067, Rating Year 2014 which includes Compliance History (CH) components from September 1, 2009, through August 31, 2014.

Classification: SATISFACTORY Rating: 2.27 Customer, Respondent, CN600376073, Baytown Energy Center.

or Owner/Operator: LLC Regulated Entity:

Classification: SATISFACTORY RN100226067, BAYTOWN ENERGY Rating: 2.27

CENTER

Complexity Points: 19 Repeat Violator: NO

CH Group: 06 - Electric Power Generation

Location: 8605 FARM-TO-MARKET ROAD 1405 NEAR BAYTOWN, TEXAS 77523-8668, CHAMBERS COUNTY

TCEQ Region: **REGION 12 - HOUSTON**

ID Number(s):

AIR OPERATING PERMITS ACCOUNT NUMBER CI0184T **AIR OPERATING PERMITS PERMIT 2133**

AIR NEW SOURCE PERMITS PERMIT 41996 AIR NEW SOURCE PERMITS REGISTRATION 49622 AIR NEW SOURCE PERMITS ACCOUNT NUMBER CI0184T AIR NEW SOURCE PERMITS EPA PERMIT PSDTX953

AIR NEW SOURCE PERMITS AFS NUM 4807100089 AIR NEW SOURCE PERMITS REGISTRATION 93224

AIR NEW SOURCE PERMITS REGISTRATION 116107 AIR NEW SOURCE PERMITS EPA PERMIT NO20 **AIR EMISSIONS INVENTORY ACCOUNT NUMBER CI0184T** INDUSTRIAL AND HAZARDOUS WASTE EPA ID

TXR000043976

INDUSTRIAL AND HAZARDOUS WASTE SOLID WASTE

REGISTRATION # (SWR) 86845

Rating Year: 2014 Compliance History Period: September 01, 2009 to August 31, 2014 Rating Date: 09/01/2014

Date Compliance History Report Prepared: January 29, 2015

Agency Decision Requiring Compliance History: Enforcement Component Period Selected: January 29, 2010 to January 29, 2015

TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.

Name: Rachel Bekowies Phone: (512) 239-2608

Site and Owner/Operator History:

1) Has the site been in existence and/or operation for the full five year compliance period? YES

2) Has there been a (known) change in ownership/operator of the site during the compliance period?

NO 3) If **YES** for #2, who is the current owner/operator? N/A

4) If YES for #2, who was/were the prior

N/A owner(s)/operator(s)?

5) If YES, when did the change(s) in owner or operator N/A occur?

Components (Multimedia) for the Site Are Listed in Sections A - J

A. Final Orders, court judgments, and consent decrees:

Effective Date: 05/25/2012 ADMINORDER 2011-1747-AIR-E (1660 Order-Agreed Order With Denial) 1

Classification: Moderate

30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 117, SubChapter B 117.310(c)(2)(A)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:Permit 41996, SC Nos. 5 and 8 PA

Special Terms and Conditions 6 OP

Description: Failed to operate within the permitted concentration limits for nitrogen oxides ("NOx") and ammonia from the

combined-cycle turbine unit exhaust stacks: EPNs CTG1, CTG2 and CTG3. Specifically, during the reporting period from August 5, 2009 to August 4, 2010, the Respondent exceeded the 3-hour rolling average concentration of 3.5 parts per million, volumetric dry ("ppmvd") for NOx 78 times, and exceeded the 10 ppmvd 1-hour rolling average limit for ammonia 108 times.

B. Criminal convictions:

N/A

C. Chronic excessive emissions events:

N/A

D. The approval dates of investigations (CCEDS Inv. Track. No.):

Item 1	May 20, 2010	(801685)
Item 2	April 08, 2011	(900051)
Item 3	November 14, 2011	(957315)
Item 4	June 15, 2012	(1013687)
Item 5	August 06, 2013	(1101162)
Item 6	January 15, 2014	(1134219)
Item 7	January 31, 2014	(1134217)

E. Written notices of violations (NOV) (CCEDS Inv. Track. No.):

A notice of violation represents a written allegation of a violation of a specific regulatory requirement from the commission to a regulated entity. A notice of violation is not a final enforcement action, nor proof that a violation has actually occurred.

1	Date: 02/	28/2014	(1134478)	CN600376073	
	Self Report?	NO		Classification:	Minor
	Citation:	30 TAC	Chanter 116	SubChantor R 116 115(c)	

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 6 PERMIT Special Term & Condition 3(C)(iii)(1) OP

Special Term & Condition 7 OP

Description: Failure to perform visible emissions observations for Cooling Tower (CWT-1) and

the Diesel Fire Water Pump. (Category C1)

Self Report? NO Classification: Minor Citation: 30 TAC Chapter 117, SubChapter B 117.345(f)(10)

itation: 30 TAC Chapter 117, SubChapter B 117.345(f)(10) 30 TAC Chapter 117, SubChapter B 117.345(f)(6) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Term & Condition 1A OP

Description: Failure to record all instances of operation for the diesel firewater pump engine.

(Category C3)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 1 PERMIT Special Term & Condition 7 OP

Description: Failure to limit carbon monoxide (CO) below the Maximum Allowable Emissions

Rate (MAER). (Category B13)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 8 PERMIT Special Term & Condition 7 OP

Description: Failure to limit ammonia (NH3) slip below the 10 ppmvd concentration limit.

(Category B14)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 5 PERMIT Special Term & Condition 7 OP

Description: Failure to limit NOx concentrations below the limit of 3.5 ppmvd. (Category B14)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)

30 TAC Chapter 122, SubChapter B 122.145(2)(A)

5C THSC Chapter 382 382.085(b)

General Terms & Conditions OP

Failure to report all instances of deviations. (Category C3) Description:

2 Date:

11/19/2014 (1193262)

CN600376073

Classification: Minor

Citation:

Self Report? NO

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

FOP ST&C 3(A)(iv)(3) OP

Description:

Failure to conduct quarterly visible emission observations of the diesel driven fire

pump (EPN: ENG). (Category C1)

Self Report?

Classification:

Moderate

Citation:

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) FOP Special Term and Condition 7 OP **NSR Special Condition 1 PERMIT**

Description:

Failure to maintain the ammonia (NH3) pounds per hour (lb/hr) below the

Maximun Allowable Emissions Rate (MAER). (Category C4)

F. Environmental audits:

Notice of Intent Date:

08/13/2012 (1035469)

No DOV Associated

G. Type of environmental management systems (EMSs):

H. Voluntary on-site compliance assessment dates:

N/A

I. Participation in a voluntary pollution reduction program:

J. Early compliance:

N/A

Sites Outside of Texas:

N/A

Component Appendices

Appendix A

All NOVs Issued During Component Period 1/29/2010 and 1/29/2015

1

Date: 02/12/2010 (781193)

CN600376073

Classification:

Self Report?

NO

For Informational Purposes Only

Citation:

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

FOP O-02133 Special Term & Condition 6 OP NSR Permit 41996 Special Condition 8 PERMIT

Description:

Failure to keep ammonia concentrations below the permitted limit. (CATEGORY

B18 Violation)

Classification:

Minor

Self Report? NO For Informational Purposes Only

Citation:

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

FOP O-02133 Special Term & Condition 6 OP NSR Permit 41996 Special Condition 5 PERMIT

Description:

Failure to keep NOx concentrations below the permitted limit. (CATEGORY B18

Violation)

Classification:

Self Report? NO For Informational Purposes Only

Citation:

30 TAC Chapter 117, SubChapter B 117.340(c)(1)(C)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

FOP O-02133 Special Term & Condition 6 OP NSR Permit 41996 Special Condition 16 PERMIT

Description:

Failure to maintain the CEMS unit. (CATEGORY B18 Violation)

2

Date:

08/31/2011

NO

(879374)

CN600376073

Classification:

Moderate

Self Report?

For Informational Purposes Only

Citation:

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 1 PERMIT Special Terms and Conditions 6 OP

Description:

Failure to meet the MAERT limits for NOx, NH3, and CO.

Classification: Moderate

Self Report?

For Informational Purposes Only

Citation:

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b)

Special Condition 16 PERMIT Special Terms and Conditions 6 OP

Description:

Failure to maintain CEMS unit.

Classification:

Moderate

Self Report? NO For Informational Purposes Only

Citation:

30 TAC Chapter 122, SubChapter B 122.143(4) 30 TAC Chapter 122, SubChapter B 122.146(2)

5C THSC Chapter 382 382.085(b) Special Terms and Conditions 8 OP

Description:

Failure to submit permit compliance certification within 30 days of the end of the

certification period.

3

Date:

03/08/2012

(982969)

CN600376073

Minor

Self Report? NO

Classification: For Informational Purposes Only

Citation:

30 TAC Chapter 117, SubChapter B 117.345(c)(1) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Special Codition 1A OP

Description:

Failure to submit four (4) stack test reports 60 days after conducting the Relative

Accuracy Test Audit

Cat C-3

Date: 11/30/2012 (1043456)CN600376073

> Classification: Minor

For Informational Purposes Only Self Report? NO

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

Special Condition 5 PERMIT Special Term and Condition 4 OP

Description: Failure to comply with permitted NOx concentration of 3.5 parts per million by

volume dry(Category B14).

Classification: Minor

For Informational Purposes Only Self Report?

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

> 5C THSC Chapter 382 382.085(b) Special Condition 8 PERMIT

Special Term and Condition 4 OP

Failure to comply with the NH3 concentration limit of 10 ppmvd (Category B14). Description:

Classification: Minor

For Informational Purposes Only Self Report?

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 16 PERMIT Special Term and Condition 4 OP

Description: Failure to comply with the NH3 30.90 pounds per hour limit (Category B14).

For Informational Purposes Only Self Report? NO

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

(1134478)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 6 PERMIT

Special Term & Condition 3(C)(iii)(1) OP

Special Term & Condition 7 OP

Description: Failure to perform visible emissions observations for Cooling Tower (CWT-1) and

the Diesel Fire Water Pump. (Category C1)

Classification: Minor

Classification:

Classification:

Minor

Moderate

CN600376073

For Informational Purposes Only Self Report? NO

Citation: 30 TAC Chapter 117, SubChapter B 117.345(f)(10) 30 TAC Chapter 117, SubChapter B 117.345(f)(6)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Term & Condition 1A OP

Description: Failure to record all instances of operation for the diesel firewater pump engine.

(Category C3)

5*

Date:

02/28/2014

For Informational Purposes Only NO

Self Report? Citation:

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 1 PERMIT Special Term & Condition 7 OP

Description: Failure to limit carbon monoxide (CO) below the Maximum Allowable Emissions

Rate (MAER). (Category B13)

Classification: Moderate

For Informational Purposes Only Self Report? NO Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 8 PERMIT Special Term & Condition 7 OP

Description: Failure to limit ammonia (NH3) slip below the 10 ppmvd concentration limit.

(Category B14)

Classification: Moderate

For Informational Purposes Only Self Report? NO

Citation:

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 5 PERMIT Special Term & Condition 7 OP

Description:

Failure to limit NOx concentrations below the limit of 3.5 ppmyd. (Category B14)

Classification:

Self Report?

NO

For Informational Purposes Only

Citation:

30 TAC Chapter 122, SubChapter B 122.143(4)

30 TAC Chapter 122, SubChapter B 122.145(2)(A)

5C THSC Chapter 382 382.085(b) General Terms & Conditions OP

Description:

Failure to report all instances of deviations. (Category C3)

6

Date:

11/19/2014

(1193262)

CN600376073

Minor

Self Report? NO For Informational Purposes Only

Citation:

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b)

FOP ST&C 3(A)(iv)(3) OP

Description:

Failure to conduct quarterly visible emission observations of the diesel driven fire

pump (EPN: ENG). (Category C1)

Classification:

Classification:

Moderate

Self Report?

For Informational Purposes Only

Citation:

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) FOP Special Term and Condition 7 OP NSR Special Condition 1 PERMIT

(781193)

Description:

Failure to maintain the ammonia (NH3) pounds per hour (lb/hr) below the

Maximun Allowable Emissions Rate (MAER). (Category C4)

Appendix B

All Investigations Conducted During Component Period January 29, 2010 and January 29, 2015

Item 1	February 11, 2010**	For Informational Purposes Only
Item 2*	May 20, 2010**	(801685) For Informational Purposes Only
Item 3*	April 08, 2011**	(900051) For Informational Purposes Only
Item 4	August 31, 2011**	(879374) For Informational Purposes Only
Item 5	October 20, 2011**	(957455) For Informational Purposes Only
Item 6*	November 14, 2011**	(957315) For Informational Purposes Only
Item 7	March 05, 2012**	(982969) For Informational Purposes Only
Item 8	May 24, 2012**	(1002679) For Informational Purposes Only
Item 9*	June 15, 2012**	(1013687) For Informational Purposes Only

^{*} NOVs applicable for the Compliance History rating period 9/1/2009 to 8/31/2014

Item 10	November 30, 2012**	(1043456) For Informational	Purposes	Only
Item 11*	August 06, 2013**	(1101162) For Informational	Purposes	Only
Item 12*	January 15, 2014**	(1134219) For Informational	Purposes	Only
Item 13*	January 31, 2014**	(1134217) For Informational	Purposes	Only
Item 14	February 28, 2014**	(1134478) For Informational	Purposes	Only
Item 15	June 06, 2014**	(1172353) For Informational	Purposes	Only
Item 16	November 19, 2014	(1193262) For Informational	Purposes	Only

^{*} No violations documented during this investigation **Investigation applicable for the Compliance History Rating period between 09/01/2009 and 08/31/2014.

			1

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



§	BEFORE THE
§	
§	TEXAS COMMISSION ON
§	
§	ENVIRONMENTAL QUALITY
	80 60 60 60 60 60 60 60

AGREED ORDER DOCKET NO. 2014-1802-AIR-E

At its ______ agenda, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding Baytown Energy Center, LLC ("Respondent") under the authority of Tex. Health & Safety Code ch. 382 and Tex. Water Code ch. 7. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent presented this agreement to the Commission.

The Respondent understands that it has certain procedural rights at certain points in the enforcement process, including, but not limited to, the right to formal notice of violations, notice of an evidentiary hearing, the right to an evidentiary hearing, and a right to appeal. By entering into this Agreed Order, the Respondent agrees to waive all notice and procedural rights.

It is further understood and agreed that this Order represents the complete and fully-integrated settlement of the parties. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable. The duties and responsibilities imposed by this Agreed Order are binding upon the Respondent.

The Commission makes the following Findings of Fact and Conclusions of Law:

I. FINDINGS OF FACT

1. The Respondent owns and operates a natural gas-fired cogeneration power plant at 8605 Farm-to-Market Road 1405 near Baytown, Chambers County, Texas (the "Plant").

- 2. The Plant consists of one or more sources as defined in Tex. Health & Safety Code § 382.003(12).
- 3. During a record review conducted from September 30, 2014 through October 10, 2014, TCEQ staff documented that the Respondent failed to include a signed certification of accuracy and completeness with a report required by Federal Operating Permit ("FOP") No. O2133. Specifically, the deviation report dated February 28, 2014 for the reporting period from August 5, 2013 through February 4, 2014 was submitted to the TCEQ Houston Regional Office without a signed certification of accuracy and completeness.
- 4. During a record review conducted from September 30, 2014 through October 10, 2014, TCEQ staff documented that the Respondent failed to operate within the permitted concentration limits for nitrogen oxides ("NOx") and ammonia ("NH3") from the Heat Recovery Steam Generating ("HRSG") Stack, Emission Point Numbers ("EPNs") CTG1, CTG2, and CTG3. Specifically, the NOx concentration limit of 3.5 parts per million by volume on a dry basis ("ppmvd"), based on a three-hour rolling average concentration, was exceeded five times from EPN CTG1 from September 28, 2013 through April 16, 2014, two times from EPN CTG2 from October 26, 2013 through December 8, 2013, and nine times from EPN CTG3 from September 3, 2013 through June 3, 2014. The NH3 concentration limit of 10 ppmvd, based on a one-hour rolling average concentration, was exceeded one time from EPN CTG1 on February 12, 2014, nine times from EPN CTG2 from September 4, 2013 through March 5, 2014, and five times from EPN CTG3 from September 4, 2013 through December 12, 2013.
- 5. The Respondent received notice of the violations on November 24, 2014.
- 6. The Executive Director recognizes that the Respondent has implemented the following corrective measures at the Plant:
 - a. On December 16, 2013, performed maintenance on the programmable logic controller to prevent inaccurate readings from the continuous emissions monitoring system;
 - b. On February 28, 2014, replaced and upgraded the catalyst for EPN CTG3 to prevent NOx and NH3 concentration limit exceedances from EPN CTG3;
 - c. On June 17, 2014, repaired the HRSG Unit tube leak that was causing inaccurate temperature readings from one of the thermocouples that indicate HRSG Unit temperature;
 - d. By August 20, 2014, conducted training on procedures for startup and for monitoring the function of various components to maintain compliance, including checking the control valve and the NH3 stop valve, for operators at the Plant;

- e. On October 23, 2014, submitted a signed certification of accuracy and completeness for the deviation report dated February 28, 2014 for the reporting period from August 5, 2013 through February 4, 2014;
- f. On November 24, 2014, replaced and upgraded the catalyst for EPN CTG2 to prevent NOx and NH3 concentration limit exceedances from EPN CTG2; and
- g. On February 14, 2015, replaced and upgraded the catalyst for EPN CTG1 to prevent NOx and NH3 concentration limit exceedances from EPN CTG1.

II. CONCLUSIONS OF LAW

- 1. The Respondent is subject to the jurisdiction of the TCEQ pursuant to TEX. HEALTH & SAFETY CODE ch. 382, TEX. WATER CODE ch. 7, and the rules of the Commission.
- 2. As evidenced by Findings of Fact No. 3, the Respondent failed to include a signed certification of accuracy and completeness with a report required by FOP No. O2133, in violation of 30 Tex. Admin. Code §§ 122.143(4) and (15) and 122.165(a)(7), Tex. Health & Safety Code § 382.085(b), and FOP No. O2133, General Terms and Conditions.
- As evidenced by Findings of Fact No. 4, the Respondent failed to operate within the permitted concentration limits for NOx and NH3 from the HRSG Stack, EPNs CTG1, CTG2, and CTG3, in violation of 30 Tex. Admin. Code §§ 101.20(3), 116.115(c), and 122.143(4), Tex. Health & Safety Code § 382.085(b), New Source Review Permit Nos. 41996, PSDTX953, and No20, Special Conditions Nos. 5 and 8, and FOP No. O2133, Special Terms and Conditions No. 7.
- 4. Pursuant to Tex. Water Code § 7.051, the Commission has the authority to assess an administrative penalty against the Respondent for violations of the Texas Water Code and the Texas Health and Safety Code within the Commission's jurisdiction; for violations of rules adopted under such statutes; or for violations of orders or permits issued under such statutes.
- 5. An administrative penalty in the amount of Sixty-Six Thousand One Hundred Eighty-Eight Dollars (\$66,188) is justified by the facts recited in this Agreed Order, and considered in light of the factors set forth in Tex. Water Code § 7.053. The Respondent has paid Thirty-Three Thousand Ninety-Four Dollars (\$33,094) of the administrative penalty and Thirty-Three Thousand Ninety-Four Dollars (\$33,094) shall be conditionally offset by the Respondent's completion of a Supplemental Environmental Project ("SEP").

III. ORDERING PROVISIONS

NOW, THEREFORE, THE TEXAS COMMISSION ON ENVIRONMENTAL QUALITY ORDERS that:

The Respondent is assessed an administrative penalty in the amount of Sixty-Six Thousand One Hundred Eighty-Eight Dollars (\$66,188) as set forth in Section II, Paragraph 5 above, for violations of TCEQ rules and state statutes. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order completely resolve the violations set forth by this Agreed Order in this action. However, the Commission shall not be constrained in any manner from requiring corrective actions or penalties for other violations that are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: Baytown Energy Center, LLC, Docket No. 2014-1802-AIR-E" to:

Financial Administration Division, Revenue Operations Section Attention: Cashier's Office, MC 214 Texas Commission on Environmental Quality P.O. Box 13088 Austin, Texas 78711-3088

- 2. The Respondent shall implement and complete a SEP in accordance with Tex. Water Code § 7.067. As set forth in Section II, Paragraph 5 above, Thirty-Three Thousand Ninety-Four Dollars (\$33,094) of the assessed administrative penalty shall be offset with the condition that the SEP defined in Attachment A, incorporated herein by reference, is implemented by the Respondent. The Respondent's obligation to pay the conditionally offset portion of the assessed administrative penalty shall be discharged upon final completion of all provisions of the SEP agreement.
- 3. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Plant operations referenced in this Agreed Order.
- 4. If the Respondent fails to comply with any of the Ordering Provisions in this Agreed Order within the prescribed schedules, and that failure is caused solely by an act of God, war, strike, riot, or other catastrophe, the Respondent's failure to comply is not a violation of this Agreed Order. The Respondent shall have the burden of establishing to the Executive Director's satisfaction that such an event has occurred. The Respondent shall notify the Executive Director within seven days after the Respondent becomes aware of a delaying event and shall take all reasonable measures to mitigate and minimize any delay.
- 5. The Executive Director may grant an extension of any deadline in this Agreed Order or in any plan, report, or other document submitted pursuant to this Agreed Order, upon a written and substantiated showing of good cause. All requests for extensions by the

Respondent shall be made in writing to the Executive Director. Extensions are not effective until the Respondent receives written approval from the Executive Director. The determination of what constitutes good cause rests solely with the Executive Director.

- 6. The Executive Director may refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings without notice to the Respondent if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.
- 7. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
- 8. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
- This Agreed Order may be executed in separate and multiple counterparts, which 9. together shall constitute a single instrument. Any page of this Agreed Order may be copied, scanned, digitized, converted to electronic portable document format ("pdf"), or otherwise reproduced and may be transmitted by digital or electronic transmission, including but not limited to facsimile transmission and electronic mail. Any signature affixed to this Agreed Order shall constitute an original signature for all purposes and may be used, filed, substituted, or issued for any purpose for which an original signature could be used. The term "signature" shall include manual signatures and true and accurate reproductions of manual signatures created, executed, endorsed, adopted, or authorized by the person or persons to whom the signatures are attributable. Signatures may be copied or reproduced digitally, electronically, by photocopying, engraving, imprinting, lithographing, electronic mail, facsimile transmission, stamping, or any other means or process which the Executive Director deems acceptable. In this paragraph exclusively, the terms "electronic transmission", "owner", "person", "writing", and "written" shall have the meanings assigned to them under TEX. BUS. ORG. CODE § 1.002.
- The Chief Clerk shall provide a copy of this Agreed Order to each of the parties. By law, the effective date of this Agreed Order is the third day after the mailing date, as provided by 30 Tex. Admin. Code § 70.10(b) and Tex. Gov't Code § 2001.142.

SIGNATURE PAGE

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

For the Commission	-
Pennyoners For the Executive Director	5(29115 Date
of Baytown Energy Center, LLC, and do agree	the attached Agreed Order in the matter of d to agree to the attached Agreed Order on behal to the specified terms and conditions. I further nent for the penalty amount, is materially relying
I understand that by entering into this Agreed certain procedural rights, including, but not li addressed by this Agreed Order, notice of an e hearing, and the right to appeal. I agree to the evidentiary hearing. This Agreed Order constitutions of the violations set forth in this Agreed Order constitutions.	mited to, the right to formal notice of violations widentiary hearing, the right to an evidentiary e terms of the Agreed Order in lieu of an itutes full and final adjudication by the
 additional penalties, and/or attorney feech Increased penalties in any future enformed and and and and and and and and and an	nt, may result in: ry; rions submitted; neral's Office for contempt, injunctive relief, ees, or to a collection agency; cement actions; eral's Office of any future enforcement actions;
Whadden Kill	4/17/15
Signature	Date
W. Thaddeus Miller	
Name (Printed or typed)	-
Authorized Representative of Baytown Energy Center, LLC	

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenue Operations Section at the address in Section III, Paragraph 1 of this Agreed Order.

Attachment A

Docket Number: 2014-1802-AIR-E

SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:	Baytown Energy Center, LLC
Penalty Amount:	Sixty-Six Thousand One Hundred Eighty-Eight Dollars (\$66,188)
SEP Offset Amount:	Thirty-Three Thousand Ninety-Four Dollars (\$33,094)
Type of SEP:	Contribution to a Third-Party Pre-Approved SEP
Third-Party Administrator:	Railroad Commission of Texas
Project Name:	Alternative Fuels Clean School Bus Replacement Program
Location of SEP:	Statewide, Preference for Chambers County

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative penalty amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The SEP Offset Amount is set forth above and such offset is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Administrator named above. The contribution will be to the **Railroad Commission of Texas** for the *Alternative Fuels Clean School Bus Replacement Program*. The contribution will be used in accordance with the SEP between the Third-Party Administrator and the TCEQ (the "Project"). Specifically, the contribution will be used to reduce nitrogen oxides, volatile organic compounds, carbon monoxide, and particulate matter emissions by replacing older diesel buses with newer buses that meet more stringent emission standards.

The Third-Party Administrator shall use the SEP Offset Amount for up to 100% of the purchase price of a propane or natural gas powered school bus that is model year 2010 or newer to public school districts and public charter schools to replace a diesel school bus that is model year 2002 or older. The SEP will be done in accordance with all federal, state, and local environmental laws and regulations.

All dollars contributed will be used for the direct cost of implementing the Project, including but not limited to supplies, materials, and equipment. Any portion of this contribution that is not spent on the specifically identified SEP may, at the discretion of the Executive Director ("ED"), be applied to another pre-approved SEP.

Baytown Energy Center, LLC Agreed Order - Attachment A

The Respondent's signature affixed to this Agreed Order certifies that it has no prior commitment to make this contribution and that it is being contributed solely in an effort to settle this enforcement action. The Respondent shall not profit in any manner from this SEP.

b. Environmental Benefit

This SEP will directly benefit air quality by reducing harmful exhaust emissions which contribute to the formation of ozone and may cause or exacerbate a number of respiratory diseases, including asthma. In addition, by encouraging less school bus idling, this SEP contributes to public awareness of environmental matters.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Administrator and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Administrator. The Respondent shall make the check payable to **Railroad Commission of Texas SEP** and shall mail the contribution with a copy of the Agreed Order to:

Alternative Energy Division Railroad Commission of Texas P.O. Box 12967 Austin, Texas 78711-2967

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the Enforcement Division SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount due to the Third-Party Administrator. The Respondent shall mail a copy of the check and transmittal letter to:

Texas Commission on Environmental Quality Enforcement Division Attention: SEP Coordinator, MC 219 P.O. Box 13087 Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this Attachment A, including full expenditure of the SEP Offset Amount and submittal of the required reporting described in Sections 2 and 3 above, the ED may require immediate payment of all or part of the SEP Offset Amount.

In the event the ED determines that the Respondent failed to fully implement and complete the Project, the Respondent shall remit payment for all or a portion of the SEP Offset Amount, as determined by the ED, and as set forth in the attached Agreed Order. After receiving notice of failure to complete the SEP, the Respondent shall include the docket number of the attached Agreed Order and a note that the enclosed payment is for the reimbursement of a SEP; shall make the check payable to "Texas Commission on Environmental Quality;" and shall mail it to:

Texas Commission on Environmental Quality Litigation Division Attention: SEP Coordinator, MC 175 P.O. Box 13087 Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP made by or on behalf of the Respondent, must include a clear statement that the Project was performed as part of the settlement of an enforcement action brought by the TCEQ. Such statements include advertising, public relations, and press releases.

6. Recognition

The Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.